

29 October, 2015

Vaasa, Finland

Technical note for Vamp 57

This technical note applies to V57 relay delivered using firmware 20.101, released to production 28 October 2015, or newer versions.

Firmware 20.xxx contains following new features:

- I> pick-up setting minimum value changed from 0,10 to 0,05 x I_n
- Number of setting groups increased from 2 to 4
- Definite time operation time delay can set to 0ms when zero delay setting enabled
- Estimated time to motor restart indication for N> and T> stages added
- ANSI code of I2>> changed to 47, previously was 46

Special note when working with firmware 20.xx

- VAMPSET file done using previous 19.xx firmware cannot be downloaded in the relay having firmware 20.xx. This means that the VAMPSET source file must be taken from a relay having firmware 20.xx
- Alternative to above is to download sample VAMPSET file from m.vamp.fi. Please note that m.vamp.fi does not contain all possible configuration combinations.